



OUR PROVEN 4 POINT LINT REMOVAL PROGRAM



1ST SERVICE POINT INSIDE THE DRYER

SYMPTOMS

- VISIBLE LINT BUILD UP
- THE DRYER IS HOT TO THE TOUCH
- THE DRYER REQUIRES ADDITIONAL DRY-TIME
- STATIC ELECTRICITY

CONSEQUENCES

- DRYER FIRE HAZARD/LOSS OF DRYER EFFICIENCIES
- DRYER BREAKDOWNS, SENSOR, RELAYS, ETC.
- WEAR & TEAR ON DRYER & LINEN INVENTORY
- STATIC EXPOSURE



2ND SERVICE POINT INSIDE THE TRANSITION VENT

SYMPTOMS

- VISIBLE LINT BUILD UP
- WORK ENVIRONMENT IS WARM
- DRYER REQUIRES ADDITIONAL DRYING CYCLE

CONSEQUENCES

- LOSS OF DRYER EFFICIENCIES
- SHUTS DOWN & NEEDS REPAIRS
- EXTRA ENERGY COSTS
- DRYER BREAKS DOWN, STATIC EXPOSURE



3RD SERVICE POINT INSIDE YOUR DRYER VENT SYSTEMS

SYMPTOMS

- VISIBLE LINT BUILD UP
- THE DRYER NOT DRYING
- VISIBLE LINT IN WORK ENVIRONMENT
- DRYER DOESN'T OPERATE AT NORMAL TEMPERATURES

CONSEQUENCES

- LOSS OF DRYER EFFICIENCIES
- DRYER OPERATES INEFFICIENTLY
- EXTRA ENERGY COSTS
- DRYER BREAKS DOWN, STATIC EXPOSURE



4TH SERVICE POINT MAKE UP AIR VENTS

SYMPTOMS

- VISIBLE LINT BUILD UP
- BLOCKED MAKE UP AIR VENTS
- BLOCKED MAKE UP AIR

CONSEQUENCES

- DRYER FIRE HAZARD/LOSS OF DRYER EFFICIENCIES
- IMPROPER DRYER OPERATIONS
- HIGH OPERATIONAL COSTS

CALL US 1-855-828-LINT (5468) | WWW.LINTCHECK.COM

Our technicians are certified professionals for electric and gas dryers.
For gas dryers, our 4 Point Lint Removal Program is carried out by TSSA-approved G2 gas technicians.
LINT CHECK™ is an approved T.S.S.A # 000181856 company.
LINT CHECK™ is a registered trade mark for DDRUS Holding Inc. This document has been copyright protected.